

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	2 6 1 3	DATE	September.28.2010
MANUFACTURER	UD Trucks Corporation		
DESCRIPTION OF DEFECT	Because the blow-by gas reducing device is not put on in the engine, it do not the vehicle conforms to Safety Regulations.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CB63BTH series	—	2005~2007	10
		TOTAL	10