

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	2615	DATE	September 30 ,2010
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		Heavy duty trucks equipped with the air suspension system have the wrong bush dimensions for the V rods that fix the rear axles to the vehicle frame. Large constant stress inputs resulting from bumps in the road, for example, may wear the circumference of the bushes. Continued use could lead to the V rods being damaged, and at worst, could lead to a driving instability.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KL-CYL23Q4	GIGA	2004-2005	82
KL-CYL23R4		2004-2005	16
KL-CYL23T4		2005	1
KL-CYL23V4		2004-2005	59
KL-CYL23V4Z		2004-2005	28
PJ-CYL51Q6		2005-2006	22
PJ-CYL51R6		2005-2006	6
PJ-CYL51T6		2005-2006	4
KL-CYL51V4		2004-2005	301
KL-CYL51V4A			
KL-CYL51V4Z		2004-2005	16
PJ-CYL51V5		2004-2005	1,403
PJ-CYL51V5A			
PJ-CYL51V5Z		2004-2005	66
PJ-CYL51V6		2005-2006	1,800
PJ-CYL51V6A			
PJ-CYL51V6Z		2005-2006	31
KL-CYL52V4		2004-2005	37
KL-CYL52V4A			
PJ-CYL52V6		2005-2006	30
PJ-CYL52V6A			
PJ-CYL77Q6	2005-2006	66	
PJ-CYL77R6	2005-2006	11	
PJ-CYL77T6	2005	5	
PJ-CYL77V6	2005-2006	150	
PJ-CYL77V6A			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PJ-CYL77V6Z	GIGA	2005-2006	17
ADG-CYL77V7		2006	1
KL-CYY51V4		2004-2005	18
KL-CYY51V4Z		2004-2005	4
PJ-CYY51V5		2004-2005	61
PJ-CYY51V5Z		2004-2005	5
PJ-CYY51V6		2005-2006	55
PJ-CYY51V6Z		2005-2006	4
KL-CYY52V4		2004-2005	9
PJ-CYY52V6		2005-2006	6
KL-EXY52J3W		2004-2005	21
PJ-EXY52J6		2005-2006	15
			TOTAL