

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2617	DATE	Oct. 7, 2010
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	On a door mirror, as adhesive is not applied to the bolt which fixes the main body of door mirror and the door mirror base, the bolt might become loose due to vibration when a vehicle is running and/or large external force. Continuous use of a vehicle with this condition may, in the possible worst case, lead to detachment of the main body of door mirror from the door mirror base, resulting in loss of rear traffic views.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-L175S	MOVE	2006-2010	528,484
DBA-L175S			
CBA-L185S			
DBA-L185S			
CBA-L375S	TANTO	2007-2010	353,522
DBA-L375S			
CBA-L385S			
		TOTAL	882,006