

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	Gai-1707	DATE	Oct.14.2010
MANUFACTURER	Scania CV AB (publ) (Hino Motors, Ltd.)		
DESCRIPTION OF DEFECT	On certain heavy duty tractors, the tightening bolts that fix the mounting plate for the fifth wheel to the frame could be loose due to inadequate design of it. , allowing the bolts come off the frame, in extreme circumstances, the fifth wheel might come off the frame.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BKG-SHD2EAJ	Hino SCANIA	2009	1
BKG-SHD2FAG		2009	1
		TOTAL	2