

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

### Domestic Vehicles

<b>CAMPAIGN No.</b>	<b>2633</b>	<b>DATE</b>	<b>October 15, 2010</b>
<b>MANUFACTURER</b>	<b>SUZUKI MOTOR CORPORATION</b>		
<b>DESCRIPTION OF DEFECT</b>	Securing screws of door mirror assembly on the mirror base may be loosened as the screws do not have stopper, when the excessive vibration and/or bending stress applied onto the threads during use. In worst case, the door mirror may be come out from the base, if the vehicle used continuously even after the screws are loosened.		

<b>TYPE</b>	<b>COMMERCIAL NAME</b>	<b>MODEL YEAR RECALLED</b>	<b>NUMBER OF VEHICLE</b>
DBA-ZC71S	<b>SWIFT</b>	<b>2007~2009</b>	<b>70,133</b>
DBA-ZC11S			
DBA-ZD11S			
DBA-ZC21S			
DBA-ZD21S			
CBA-ZC31S			
DBA-YA11S	<b>SX4</b>	<b>2007~2009</b>	<b>12,955</b>
DBA-YB11S			
DBA-YC11S			
CBA-YA41S			
CBA-YB41S			

<b>DBA-MF22S</b>	<b>MR WAGON</b>	<b>2009</b>	<b>6,182</b>
<b>CBA-MF22S</b>			
<b>DBA-HG21S</b>	<b>CERVO</b>	<b>2009</b>	<b>1,347</b>
<b>CBA-HG21S</b>			
<b>DBA-MG22S</b>	<b>MOCO</b>	<b>2009</b>	<b>19,426</b>
<b>CBA-MG22S</b>			
		<b>TOTAL</b>	<b>110,043</b>