

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) Import Vehicles

CAMPAIGN No.	2 6 3 0	DATE	October.19.2010
MANUFACTURER	NIPPON FRUEHAUF COMPANY LIMITED		
DESCRIPTION OF DEFECT	In the fuel hose joint of the fuel tank, there is the one with an improper combination of inside diameters of the fuel hose. Therefore, the fuel might leak in the worst case when keeping using it.		

TYPE	COMERCAIL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-NPR85AN	ELF	2007~2009	7 2 units
BDG-NPS85AN		2008~2009	4 units
BKG-NJR85AN		2008	8 units
BKG-NMR85AN		2008~2010	5 units
BKG-NPR85AN		2007~2010	4 4 units
KC-NPR70LYR		1998	1 unit
KC-NPR71LV		1996~1999	1 5 units
KK-NPR71LV		2000	1 5 units
KK-NPR72LAV		2001	1 unit
KK-NPR72LV		2000~2001	3 units
KK-NPR75LR		2004	1 unit
KK-NPR75PR		2001	1 unit
KK-NPR75P		2001	1 unit
KR-NPR72LAV		2003	1 unit
KR-NPR72PAV		2003	1 unit
KR-NPR81LV		2004	4 units
KR-NPR81PV		2003	3 units
PA-NPR81N		2004~2007	1 0 units
PB-NPR81AN		2004~2006	2 5 units
PB-NPS81AN		2004	1 unit
PDG-NPR75N		2007	6 units
PKG-NPR75N		2008~2010	2 6 units
		TOTAL	2 4 8 units