

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	2631	DATE	October 22, 2010
MANUFACTURER	Komatsu Utility Co. , Ltd.		
DESCRIPTION OF DEFECT	The connecting point between power board and lead-plate of the power supply controller might produce heat due to the improper connecting condition. Therefore if a machine is continuously used, the electronic part in the power board may be damaged, and in the worst case a machine may not be able to travel.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAF-SM236	FB15HB	2007~2010	37
ZAF-SM237	FB18HB,FB20AHB	2007~2010	11
ZAF-M254	FB25HB	2008~2010	9
TOTAL			57