

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2637	DATE	Oct.28 2010
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	Due to improper machining of the torque converter housing, the engine and the automatic transmission may be misaligned with each other on some vehicles. If the vehicle continues to be used in this condition, the drive plate may break. In the worst case, the vehicle will become unable to drive.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PA-FB70BB	FUSO CANTER GUTS	2005~2007	731
PA-FD70BB		2005~2007	231
PDG-FB70B		2007~2008	41
PDG-FD70B		2007~2007	24
		TOTAL	1,027