

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

|                       |  |      |             |
|-----------------------|--|------|-------------|
| CAMPAIGN No.          | 2 6 3 4  | DATE | Oct.28.2010 |
| MANUFACTURER          | N I S S A N  |      |             |
| DESCRIPTION OF DEFECT | The welds between the rear spring mounting bracket, which holds the spring of the rear suspension system on the body, and the side member of the body might be incomplete on some vehicles. If the vehicle continues to be driven in this condition, the subject bracket may be moved, and in an extreme case, the rear spring may come off the vehicle. |      |             |

| TYPE     | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLES |
|----------|-----------------|---------------------|--------------------|
| DBA-C25  | NISSAN SERENA   | 2010                | 450                |
| DBA-CC25 |                 |                     | 926                |
| DBA-SC25 | SUZUKI LANDY    |                     | 23                 |
|          |                 | TOTAL               | 1,399              |