

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic, Import Vehicles

CAMPAIGN No.	Gai-1 7 1 3	DATE	November.4.2010
MANUFACTURER	VOLVO LOGISTICS CORPORATION JAPAN CO., LTD.		
DESCRIPTION OF DEFECT	Due to the inapplicable fixing of cable clamp for the starter, the cable and clamp are compressed each other. If the vehicles are being operated in this condition, there is a risk to get damaged on the coating for the cable and clamp. And they will get a short circuit and catch fire in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Fumei	—	1995~1999	155
		TOTAL	155