

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic /  Import Vehicles

Campaign No.	2649	Date	11 November,2010
Manufacture	CATERPILLAR JAPAN LTD.		
Description of Deffect	Wheel installation bolts may loosen, due to improper control of the bolts tightening torque. In the worst case, the wheel comes off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDP-SAT	910H	2010	40
		TOTAL	40