

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2655	DATE	Nov. 17, 2010
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	In the vehicles equipped with the Daihatsu dealer optional washer fluid heater, due to insufficient lap length of the O-ring for preventing the fluid from leaking from the heater, there is a possibility that the washer fluid may penetrate into the space in which the heater control circuit is located. This condition could cause the control circuit to burn out, and in the worst case, result in fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-J200G	BEGO	2006-2009	16
CBA-J210G			106
CBA-J210E	RASH		3
		TOTAL	125