

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2 6 6 3	DATE	N o v . 3 0 . 2 0 1 0
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Some condensers that are used inside a set of a speedometer of which specifications are different have been installed. Because of this reason, there is a possibility that the speedometer may not work.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
E B J - S E 4 4 J	CYGNUS-X XC125	2 0 1 0	1 , 5 9 2
	CYGNUS-X XC125SR	2 0 0 9 ~ 2 0 1 0	7 9 0
TOTAL			2 , 3 8 2