

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	2667	DATE	December 1 ,2010
MANUFACTURER		ASUKAITECH Co.,LTD.	
DESCRIPTION OF DEFECT		The supports for installing the fuel tank lack strength. They may be cracked by vibration while the vehicle is moving. Continued use could lead to the advancement of cracks, and at worst, the fule tank could drop off the vehicle.	

TYPE	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
PDG-FSS90S1	FORWARD	2009	5
		TOTAL	5