

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2672	DATE	December 9, 2010
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	On vehicles with 14 inch steel wheels, outer diameter of full wheel caps were manufactured in the larger value. If the excessive stress is applied on the tires like riding on the curbstone, side wall of the tire is interfered with the full wheel cap. In worst case, the full wheel cap may be come out from the vehicle and the cap dropped may obstruct the traffic flow.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-MK21S	PALETTE	2008~2010	42,270
CBA-MK21S			
DBA-ML21S	ROOX	2009~2010	6,852
		TOTAL	49,122