

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2673	DATE	December 9, 2010
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	Back door on the certain vehicles may not be securely closed, as the locking mechanism does not activate due to manufacturing failure of the plastic body of door latch. In worst case, the back door of the vehicle may be opened and the goods in luggage room be dropped during driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-MH23S	WAGON R	2010	69,551
CBA-MH23S			
DBA-HA25S	ALTO	2010	31,457
HBD-HA25V			
DBA-MK21S	PALETTE	2010	28,768
CBA-MK21S			
DBA-HE22S	ALTO LAPIN	2010	16,231
CBA-HE22S			
DBA-MJ23S	AZ-WAGON	2010	10,142
CBA-MJ23S			
DBA-HB25S	CAROL	2010	4,690
DBA-ML21S	ROOX	2010	16,853
CBA-ML21S			
		TOTAL	177,692