

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	Gai-1721	DATE	Dec.9.2010
MANUFACTURER	Scania CV AB (publ) (Hino Motors, Ltd.)		
DESCRIPTION OF DEFECT	On certain heavy duty tractors, due to insufficient fixation of a fuel injection pipe to the common rail of the engine, the fuel injection pipe can have high stress at the joint area where the pipe and the common rail are connected by excessive force caused by engine vibration. Therefore, if the vehicle is continue to be used as it is the fuel pipe can crack, resulting in fuel leaks.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BKG-SHD2EAG BKG-SHD2EAJ	Hino SCANIA	2007~2009	102
BKG-SHD2FAG BKG-SHD2FAJ		2008~2009	33
		TOTAL	135