

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	2664	DATE	December 10. 2010
MANUFACTURER	Komatsu Utility Co. , Ltd.		
DESCRIPTION OF DEFECT	Due to lack of strength of front wheel, crack might be generated on the wheel in the vehicle which solid tires are installed. Therefore if a vehicle is continuously used under the above condition, the front wheel might be damaged in the worst case and a machine may not be able to travel, due to falling off of a front tire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SB-M166T	—	2007	1
SB-M166T(KAI)	—	2007	1
		TOTAL	2