

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2 6 7 5	DATE	December 16 , 2010
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	There is a risk of dropping of rear track unit as a result of crack on the frame due to insufficient strength and continuous use of the frame that the track system is attached.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
KK-MK122HS KAI	CONDOR	HR40T-3	1999	1
KK-MK122ES KAI			1999	1
KK-MK122GS KAI			1999	4
KK-MK122BS KAI			1999~2001	108
KK-MK122CS KAI		GB80WHA-1	2001	5
KK-MK12A KAI		HR40T-3	2001	11
		GB80WHA-1	2003~2004	4
			2003~2004	7
		TOTAL	141	