

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2684	DATE	Jan, 11, 2011
MANUFACTURER	KYOKUTO KAIHATSU KOGYO CO.,LTD 6-1-45 Koshienguchi Nishinomiya-city Hyogo-pref. Japan		
DESCRIPTION OF DEFECT	On petroleum aluminum tank semi-trailer 20kL single axle, Crack damage may occur on bogie frame during running and/or braking cyclic load by deficiency in durability of suspension hanger installation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KL20-17AS1	Petroleum tank semi-trailer	2000	1
KL20-17AS2	Petroleum tank semi-trailer	2000-2001	2
KL20-17AS3	Petroleum tank semi-trailer	2000	2
KL20-17CS1	Petroleum tank semi-trailer	2000-2001	4
KL20-47AS1	Petroleum tank semi-trailer	2000-2004	5
KL20-47AS2	Petroleum tank semi-trailer	2001-2005	12
KL20-17CS2	Petroleum tank semi-trailer	2001-2002	2
KL20-17AS4	Petroleum tank semi-trailer	2001-2006	14
KL20-17AS5	Petroleum tank semi-trailer	2001	2
KL20-17AS6	Petroleum tank semi-trailer	2003	1
KL20-17CS3	Petroleum tank semi-trailer	2002-2007	8
KL20-17AS7	Petroleum tank semi-trailer	2002	1
KL20-17AS9	Petroleum tank semi-trailer	2004	1
KL20-17CS4	Petroleum tank semi-trailer	2005	1
KL20-17AS91	Petroleum tank semi-trailer	2005	1
KL20-17AA1	Petroleum tank semi-trailer	2006	2

KL20-37AS1	Petroleum tank semi-trailer	2006-2007	6
KL20-17AA2	Petroleum tank semi-trailer	2006	3
KL20-37AS2	Petroleum tank semi-trailer	2006	1
KL20-17AA3	Petroleum tank semi-trailer	2007	1
KL20-17AA4	Petroleum tank semi-trailer	2007	1
KL20-17AA5	Petroleum tank semi-trailer	2007	2
KL20-47AS3	Petroleum tank semi-trailer	2007	1
TOTAL			74