

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2687	DATE	Jan.11 2011
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some four-wheel-drive double cab fire engines, cracks may occur in the frame due to insufficient strength. If the vehicle continues to be used in this condition, the cracks may grow and lead to a breakage of the frame. In the worst case, the vehicle will be unable to drive.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KK-FG72EC	FUSO CANTER	2002~2004	173
		TOTAL	173