

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-1731	DATE	Jan. 26, 2011
MANUFACTURER	DAIHATSU (PT. Astra Daihatsu Motor)		
DESCRIPTION OF DEFECT	Due to improper shape of the metal fitting at the rear section of spare tire carrier, it is possible that the rear fitting section of spare tire carrier may crack depending on dispersion of fitting angle of front fitting section of spare tire carrier and vibration while driving. Continuous use of such vehicle with this condition may cause the rear fitting section of spare tire carrier to break, resulting in spare tire falling off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABF-S402U	TOWN ACE/LITE ACE	2008-2010	5,956
ABF-S412U			219
		TOTAL	6,175