

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	2701	DATE	February 3 ,2011
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	In the CNG light-duty trucks, it has been found that the speedometer might indicate a lower speed than an actual speed due to an inadequate speed computing program of the engine control module (ECM).		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
NFG-NJR82AN SFG-NJR82AN	ELF	2007-2010	86	
NFG-NKR82XAN SFG-NKR82XAN		2007-2010	116	
NFG-NLR82AN NFG-NLR82N SFG-NLR82AN		2007-2010	204	
NFG-NMR82AN NFG-NMR82N SFG-NMR82AN SFG-NMR82N		2007-2010	865	
PDG-NPR75N (kai)		2007	3	
NFG-NPR82XAN NFG-NPR82XN SFG-NPR82XAN SFG-NPR82XN		2007-2010	1,469	
NFG-AJR82AN		ATLAS	2008-2009	3
NFG-AKR82XAN			2008-2009	5
NFG-ALR82AN			2008	1
NFG-AMR82AN SFG-AMR82AN			2009-2010	5
NFG-APR82XAN NFG-APR82XN	2008-2009		2	
NFG-BJR82AN	CONDOR	2008	2	
NFG-BKR82XAN		2007-2008	3	
NFG-BMR82AN NFG-BMR82N		2008-2010	10	
NFG-BPR82XAN NFG-BPR82XN SFG-BPR82XAN		2007-2010	29	
NFG-LJR82AN		TITAN	2008	1
NFG-LMR82AN	2007-2008		8	
NFG-LPR82XAN SFG-LPR82XAN	2007-2010		4	
		TOTAL	2,816	