

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	2714	DATE	Mar. 3.2011
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain heavy duty tractors, an incorrect dimension for the front fitting radius had registered as the specification of it. This can cause that the trailer control valve at the cab back to be hit and broken if the trailer with the front fitting radius close to specification had connected and that the spring brake of the trailer to be functioned by a leakage of the brake air resulting the vehicle unable to move if the worst comes.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-SH1EDAG LKG-SH1EDAJ	Hino Profia	2010	66
LKG-SH1EEAG		2010	2
LKG-SH1EGAG		2010	3
LDG-SS1EKAA		2010	5
LDG-SS1EKAAKAI		2010	1
		TOTAL	