

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2728	DATE	Mar. 29 2011
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty trucks with a box type muffler, a wrong urea dosing nozzle is installed. If the vehicle continues to be used in this condition, crystallization of urea may occur, resulting in clogged nozzle or muffler.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDG-FP54VDR	FUSO	2009	1
LDG-FV50VJR		2010~2010	10
LKG-FP54VDR		2010~2010	161
LKG-FP54VER		2010~2010	39
LKG-FP54VGR		2010~2010	9
		TOTAL	220