

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	2740	DATE	April 19 ,2011
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		For the brake air hoses of the heavy-duty trucks, there is a possibility that the air hose may get into the gap between the air pipe clip fixing bolt and the protector due to the inappropriate location of the hose mounting. In the worst case, a hole may be made in the air hose, and this may result in the reduction of braking force.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LKG-CYH77A	GIGA	2010	7
LKG-CYJ77A LKG-CYJ77AA		2010	318
LKG-CYJ77AL		2010	5
LKG-CYJ77AZ		2010	6
		TOTAL	336