

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2743	DATE	May, 10, 2011
MANUFACTURER	KYOKUTO KAIHATSU KOGYO CO.,LTD 6-1-45 Koshienguchi Nishinomiya-city Hyogo-pref. Japan		
DESCRIPTION OF DEFECT	On heavy-duty liquid transportation truck equipped with air suspension, the bracket for spare tire carrier installed between chassis frames in the rear doesn't have enough durability.As a result, vibrating during moving, there is a possibility that the bracket could crack and spare tire		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KC-FR2PZFG	PROFIA	1999	2
KS-GN2PPWG	PROFIA	2004-2005	7
KS-FR2PPWG	PROFIA	2005	1
PK-GN2PPWG	PROFIA	2006-2007	3
BDG-GN1APYG	PROFIA	2007-2010	6
BKG-FR1APYG	PROFIA	2007-2008	4
KC-FU549UZ	SUPERGREAT	1996	1
KC-FU540UZ	SUPERGREAT	1998-1999	7
KL-FU54JNY	SUPERGREAT	2004-2005	2
KL-FT54JNY	SUPERGREAT	2004-2006	4
PJ-FT54JNY	SUPERGREAT	2005-2006	3
PJ-FU54JZ	SUPERGREAT	2006	1
PJ-FT54JY	SUPERGREAT	2006	1
BDG-FU54JY	SUPERGREAT	2008-2009	2
BDG-FT54JY	SUPERGREAT	2008	1
KC-CYL81V2	GIGA	1998	1

KC-CYL23V2W	GIGA	1998-1999	12
KC-CYL50V2W	GIGA	1998-1999	6
KC-CYL81V2W	GIGA	1999	2
KL-CYL23Q4	GIGA	2004-2005	2
LKG-CYL77AM	GIGA	2010	1
LKG-FTR90T2	FORWARD	2011	2
KL-CD48LVS	—	2003	1
ADG-CV2YL	—	2009	2
		TOTAL	74