

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2747	DATE	May. 17. 2011
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	With regard to front brake, material for the cable end cover has been found lacking suitability. This can, through frequent repetition of the parking lever operation, which may be required when stopping or parking on a hill, slope or the like, cause the inner wire to break and result in the front brake failure.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBJ-JA07	SUPER CUB 110PRO	2009~2011	4,856
	SUPER CUB 110MD	2009~2011	25,677
		TOTAL	30,533