

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-1756	DATE	May. 27, 2011
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	As the pressure gauge of the first axle which indicates the internal pressure of the container for the breaking device in the vehicle driver's cabin does not have the mark of minimum effective operation pressure level, these vehicles are in non-conformant with road transport vehicle safety standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
FAUN	ATF60J-3	2009-2011	9
		TOTAL	9