

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2758	DATE	June. 2. 2011
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	With regard to a sensor that automatically turns off the engine in the event of a tip-over, it may resonate at certain engine speeds because of inadequacy in its vibration-proof structure, causing the internal pendulum for detecting inclination to be displaced to the threshold level of tip-over detection. Should this happen, the sensor would detect such a displacement falsely as a tip-over and the engine could be thereby shut off suddenly whilst in operation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-RC50	SHADOW	2009~2011	125
EBL-RC53	SHADOW Phantom	2009~2011	573
EBL-RC56	SHADOW	2009~2011	80
		TOTAL	778