

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No	2761	DATE	June-17-2011
MANUFACTURER	Yano Special Vehicle Manufacturing Co, Ltd		
DESCRIPTION OF DEFECT	In the axle of an in-vehicle trailer, [gata] is caused in the axle when the slide hiss installed in the sliding area in the axle expansion and contraction part is worn out by the expansion and contraction of the axle when the vehicle unloading working, the weld of the locking device that fixes the axle expansion and contraction by the vibration etc. when running cracks when keeping using it under such a condition, and, in the worst case, the axle might be fractured.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ASZ122		1988～1988	3
ASZ127A		1989、1990	2
ASZ127B		1990、1990	2
ASZ127C		1992	1
ASZ133		1990～1993	4
ASZ133A		1991、1991	2
ASZ140		1990	1
ASZ141		1989～1990	3
ASZ145	-	1992	1
ASZ145A		1993	1
ASZ156A		1991	1
ASZ166		1991	1
ASZ166A		1991～1993	5
ASZ178		1993	1
ASZ183A		1993	1
ASZ302		1994、1994	2
ASZ303		1994	1

ASZ308		1994	1
ASZ315		1994	1
ASZ316		1994	1
ASZ329		1995、1995	2
ASZ339		1995、1995	2
ASZ345		1995	1
ASZ345A		1995	1
ASZ348		1995	1
ASZ350		1995	1
ASZ353		1996	1
ASZ354		1995	1
ASZ361		1996～1997	3
ASZ364		1996	1
ASZ365	-	1996～1997	10
ASZ365A		1997～1997	3
ASZ365B		1997、1997	2
ASZ367		1997、1997	2
ASZ370		1997	1
ASZ371		1997、1997	2
ASZ371A		1998～1998	3
AZ372		1997～1999	5
ASZ373		1997、1999	2
ASZ373A		1998～1998	3
ASZ373B		1998～1998	5
ASZ375		1997～1998	4
ASZ375A		1998	1
ASZ378		1998、1999	2

ASZ387	-	1999	1
ASZ388		1999	1
AZ390		1999	1
AZ393		1999	1
ASZ394		1999	1
			TOTAL 99