

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic /  Import Vehicles

CAMPAIGN No.	2770	DATE	17, June 2011
MANUFACTURER	HITACHI CONSTRUCTION MACHINERY CO, LTD.		
DESCRIPTION OF DEFECT	Because of the strength of pipe installing part which pipe is installed on the end plate of the muffler does not enough. Therefore, there is possibility that the end plate of the muffler will crack by the engine vibration.		
	The structure of the muffler has the cover plate which is fixed to the pipe on the endplate of the muffler may be easily removed.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARKS
68C	JR300-3	2006-2007	5	:5
JDS-M17	JR300-3	2007-2011	12	:12 :3
TOTAL			17	:17 :3

NOTE: The vehicles which are not applicable may also included in the range of the car for a recall.