

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

|                       |  |      |              |
|-----------------------|--|------|--------------|
| CAMPAIGN No.          | 2763   | DATE | June 21.2011 |
| MANUFACTURER          | YANMAR CO.,LTD.  |      |              |
| DESCRIPTION OF DEFECT | In steering system, there is the possibility that the steering operation is malfunctioned, because the clutch can not be disengaged by the ball clutches stoppage in the right/left power train. |      |              |

| TYPE  | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|-------|-----------------|---------------------|-------------------|
| T60A  | YG8             | 2010<br>2011        | 46                |
| TOTAL |                 |                     | 46                |