

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2764	DATE	June 21.2011
MANUFACTURER	YANMAR CO.,LTD.		
DESCRIPTION OF DEFECT	<p>There is the possibility that the reinforce material is not welded properly.</p> <p>With continuous usage of the machine without proper welding, in worst case, the machine may not be in running condition, because the frame may be damaged and the crawler may come off by the drive sprocket dis-alignment.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-	AE334	2011	1
TOTAL			1