

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2779	DATE	Jul. 7 2011
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some large-sized buses, due to the inappropriate shape of the engine hanger, cracks may occur as a result of engine vibration. If the vehicle continues to be used in this condition, the cracks will progress and the engine hanger may drop off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BKG-MS96JP	FUSO AERO ACE	2007~2010	1,378
BKG-MS96JP	FUSO AERO QUEEN	2007~2010	290
BKG-MU66JS	FUSO AERO KING	2008~2010	44
BKG-AS96JP	—	2007~2010	68
TOTAL			1,780