

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

|                       |   |      |            |
|-----------------------|---|------|------------|
| CAMPAIGN No.          | 2780  | DATE | Jul.7 2011 |
| MUNUFACTURER          | Mitsubishi Fuso Truck and Bus Corporation   |      |            |
| DESCRIPTION OF DEFECT | On some heavy-duty trucks with front tandem axles, the clearance between the power steering pipe and mudguard cover may be insufficient. If the vehicle continues to be used in this condition, the power steering pipe may interfere with the mudguard cover due to vibration during driving and be damaged. This will cause power steering oil leaks and, in the worst case, significant increase in steering effort. |      |            |

| TYPE       | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|------------|-----------------|---------------------|-------------------|
| LKG-FS50VZ | FUSO            | 2010~2011           | 39                |
| LKG-FS54VY |                 | 2010~2011           | 53                |
| LKG-FS54VZ |                 | 2010~2011           | 753               |
| LKG-FS55VY |                 | 2010~2011           | 2                 |
| LKG-FS55VZ |                 | 2010~2011           | 169               |
|            |                 | TOTAL               | 1,016             |