

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2784	DATE	July 21, 2011
MANUFACTURE	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	Due to inappropriate assembling of ventilation hose on canister which prevents evaporative gas from being emitted to the atmosphere, the ventilation hose may get caught between under body and fuel tank in some vehicles. Under this condition, purge flow amount decreases and this causes insufficient purge of the fuel vapor from the canister. As a result, excessive levels of evaporative gas may be emitted.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-DEJFS	Mazda DEMIO	2011	86
		Total	86