

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2783	DATE	July 28, 2011
MANUFACTURE	Caterpillar Japan LTD		
DESCRIPTION OF DEFECT	<p>There is a possibility that a proper signal is not output to the transmission electronic control module from the transmission shift lever in the lever operating process due to an unstable quality of the internal diode. It may occur missing of gear speed and in the worst case, the machine might not be operated forward or/and rear direction.</p> <p>Therefore it is necessary to replace the transmission shift lever with good quality of internal diode.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SC-B9Y	938G II	2007~2008	43
JDS-J5J	950H	2007~2008	54
JDS-J6J	962H	2007~2008	6
JDS-A6J	966H	2007~2009	11
JDS-A8J	980H	2008~2009	2
		TOTAL	116

Note: