

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	2791	DATE	July 28 ,2011
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	In areal platform vehicles and pole setters of light-duty trucks, strength of their frame was found to be insufficient and thus if they are repeatedly used in condition where the body is hugely twisted at an abrupt turning, the underside of the frame develops a crack in some cases. Therefore if the vehicle remains used as such, the crack may progress and the frame could break in the worst case scenario.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
U-NKR63EPN	ELF	1993-1995	444
U-NKR66E U-NKR66EPN KC-NKR66E KC-NKR66EP		1993-1997	3,978
KC-AKR66E KC-AKR66EP	ATLAS	1995-1997	575
KC-BKR66E KC-BKR66EP	CONDOR	1995-1997	106
		TOTAL	5,103