

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	GAI-1768	DATE	July 28, 2011
MANUFACTURE	Caterpillar UK LTD (Caterpillar Japan LTD)		
DESCRIPTION OF DEFECT	There is a possibility that a proper signal is not output to the transmission electronic control module from the transmission shift lever in the lever operating process due to an unstable quality of the internal diode. It may occur missing of gear speed and in the worst case, the machine might not be operated forward or/and rear direction. Therefore it is necessary to replace the transmission shift lever with good quality of internal diode.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SC-WMB	924G	2007	1
SC-WGX	924GZ	2007~2008	35
SC-WLG	928G	2007~2008	9
EDR-JTM	924H	2009~2010	3
EDR-PED	924HZ	2008~2010	28
EDR-FTD	930H	2009	1
		TOTAL	77

Note: