

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-1769	DATE	July 28, 2011
MANUFACTURER	Chrysler Group LLC (Japanese Importer : Chrysler Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	Due to improper shape of fender inner panel located in both LH and RH of front fender, there is a possibility of the interference of brake line nearly installed. Because of this reason, a hole will be made on brake pipe may cause leak of fluid. In the worst case, function of brake system will be lost.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-JK38L	Jeep Wrangler Unlimited	2007-2010	2,372
ABA-JK38S	Jeep Wrangler	2007-2010	779
		Total	3,151