VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	Gai-1770	DATE	July 28, 2011		
MANUFACTURER	Chrysler Group LLC (Japanese Importer : Chrysler Japan Co., Ltd.)				
DESCRIPTION OF DEFECT	During production process of front axle and rear axle, there may be improper application of anti corrosion paint. In case paint was applied excessively between axle and other parts, due to vibration during driving lead crack of paint and decrease of tightening torque. Because of this, these bolts and nuts might get loose. If the vehicle is driven further, noise will be generated from under body and in the worst case stable driving will not be kept.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLES
ABA-JK38L	Jeep Wrangler Unlimited	2010		116
			Total	116