

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	2795	DATE	August 11, 2011
MANUFACTURER	Komatsu Co. , Ltd.		
DESCRIPTION OF DEFECT	<p>On a power supply controller of an electric forklift, a wire might be melt down due to improper wire diameter.</p> <p>Therefore if a machine is continuously used under its condition, electric parts might be damaged and in the worst case, a machine can not travel.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAF-M254	FB20HB, FB25HB	2008~2011	13
ZAF-M254K	FB25HB	2011	2
TOTAL			15