

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	2796	DATE	August 11, 2011
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	Due to improper harness arrangement, which is main harness of the control valve, the harness might be damaged due to contact with a plate. Therefore, a machine can not travel due to fuse damage .		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDP-M250	FD35N,FD40N	2008~2010	15
KDP-M252	FD35,FD40,FD45,FD50A	2008~2010	55
EBT-M251	FG35N,FG40N	2009	2
		TOTAL	72