

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	2801	DATE	August 11 ,2011
MANUFACTURER	NIPPON TREX CO., LTD.		
DESCRIPTION OF DEFECT	In the semitrailer of shape with high center of gravity amount,when turning, an enough evaluation was not done to the axle and the wheel hub of growing of the stress that acted repeatedly.Therefore, the crack might occur in the wheel hub. As a result, the wheel hub is damaged when keeping using it with there a crack in the wheel hub, and, in the worst case, the wheel might drop out.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TNF22201	—	1996～1997	5
TNF22202	—	1995～2000	27
TNF222AC	—	1994～1995	16
TNF222AD	—	1994	1
TNF222AE	—	1994～1995	51
TNF222AF	—	1994	2
TNF222AH	—	1995	1
TNF222AJ	—	1996	3
TNF222AK	—	1997	2
TNF223AA	—	1997	1
TNF22401	—	1995～2000	39
TNF224AA	—	1994～1997	16
TNF224AB	—	1995	2
TNF224AC	—	1994～1995	2
TNF224AF	—	1995	3
TNF224AG	—	1995	1
TNF224AH	—	1997～1999	3
TNF227AA	—	1994	2
TNF228AA	—	1995	1
TNF228AB	—	1999	1
TNF228AC	—	1999～2000	2
TNF236AA	—	2000	2
TDA224AD	—	1995	1
TDA226AC	—	1996	2
TDA226AE	—	1997	1
TDA228AA	—	2000	1
TDS220AD	—	1997	1
TDS224AA	—	1998	1
TLS223AB	—	1999	1
TMS217AA	—	1997	1
VFB24101	—	1995～1999	28

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VFB24102	—	1996～1999	26
VLB24101	—	1997	7
VPB24101	—	1996～2000	19
VPD241AM	—	1995	1
CT220SD	—	1995～1999	135
CTB22001	—	1998～1999	51
CTB220AK	—	1999～2000	14
CTB220AL	—	2000	1
CTB230AD	—	1999	1
CTB233AG	—	1996	15
CTB233AH	—	1998	2
CTB237AA	—	1998	3
CTB237AB	—	1998	2
CTC239AC	—	1998	1
CTS220AA	—	1998	1
CTS239AA	—	1999	1
CTS240AB	—	1995～1999	32
CTS240AC	—	1995～1999	19
CTS240AG	—	1998	2
CTS240AH	—	1999	1
CTS240AK	—	2000	3
		TOTAL	557