

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-1773	DATE	22/Aug/2011
MANUFACTURER	VOLVO CARS CORPORATION		
DESCRIPTION OF	Volvo Car Corporation (VCC) has decided to carry out a safety recall on a limited number of Volvo S80/S60/V70 and V60 vehicles (model year 2011-2012), equipped with 1.6 liter petrol/flexi-fuel engine or 1.6 liter diesel engine. VCC investigations have identified a potential fluid leakage in the power steering system. If this condition would occur you may notice heavy steering and noise. In a worst case scenario this may lead to a sudden loss of power steering assistance without any prior warning. Depending on the driving situation this may lead to an unsafe situation. The corrective action will be to replace the upper power steering return pipe.		
DEFECT			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VOLVO	S60	2011	642
	V60	2011	1
	V70	2011	117
TOTAL			760