

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic  Import Vehicles

CAMPAIGN No.	GAI-1777	DATE	August 31, 2011
MANUFACTURE	KTM-SPORTMOTORCYCLE AG (Japanese Importer : KTM JAPAN K.K. )		
DESCRIPTION OF DEFECT	The torque for the screw connection of the two brake caliper halves is partially considerably below specification. This problem can cause a loss in brake fluid and brake pressure and consequently lead to inadequate brake performance.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KTM125DUKE	125DUKE	2011	299
		TOTAL	299