

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2815	DATE	September—6—2011
MANUFACTURER	TOKYU CAR SPV CORPORATION		
DESCRIPTION OF DEFECT	<p>In the production of the tank-truck, because the endurance strength of cross piping made by aluminum alloy is insufficient, There is a possibility that the crack occurs in cross piping made by aluminum alloy by the inner pressure when the pump is used.</p> <p>Therefore, there is a possibility that the load goods leak when keeping using it under such a condition.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PJ-CYG77P6	—	2005~2007	6
PDG-CYE77P8	—	2008、2010	2
PDG-CYG77P8	—	2010	1
KL-CV27E	—	2005	20
ADG-CV2YL	—	2005~2010	35
LDG-CV5YL	—	2010	1
KL-FT50JNY	—	2005	5
PJ-FT50JNY	—	2005	7
PJ-FT50JY	—	2006	7
PK-GN2PPWG	—	2006	1
PK-GN2PPWA	—	2006	16
BDG-GN1APYA	—	2007~2010	12
LDG-GN1APBA	—	2011	2
			TOTAL 115