

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	GAI-1774	DATE	September 7, 2011
MANUFACTURER	Audi AG (Japanese Importer : Audi Japan KK)		
DESCRIPTION OF DEFECT	<p>Due to production tolerances it is possible, that the fuel supply hose may touch and rub the heat shield in the engine compartment which in rare cases this could lead to a small fuel leak. in worst case this could lead to fire.</p> <p>On the affected vehicles the edge of the heat shield must be modified and the fuel supply hose must be checked for damage and repaired or replaced if necessary.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-42BUJF	R8 Spyder 5.2 FSI quattro	2010	18
		2011	19
		TOTAL	37