

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

CAMPAIGN No.	2799	DATE	September 8, 2011
MANUFACTURER	SUMITOMO NACCO MATERIALS HANDLING CO., LTD.		
DESCRIPTION OF DEFECT	On the fuel filter between the fuel tank and the engine, there is a potential of the fuel leaking occurred because insufficient press of connecting part of case. If the truck is being used in such condition, the fuel filter is potentially leaks gasoline fuel.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBT-G1L	FG15PXI	2010	1
EBT-G2K	FG25PXI	2008	1
EBT-G3G	FG30PXI	2009~2011	6
EBT-SG1J	FG09PXI, FG10PXI, FG14PXI, FG15PXI, FG18PXI, FG20PXI	2008~2011	70
EBT-SG2H	FG20PXI, FG25PXI	2008~2011	33
		TOTAL	111